Work Order Thursday, July 14,								LL 1111.07 T-1757			'.	Page 1
Revision ID: Item Name: An		tart Qty: 4.00 teq'd Qty: 4.00			Accept	Cust Item I				Setup Sta		1114 11 11 11 11 11 11 11
	Process Plan: QC:		Date:	07-/7	Tooling: _		nte:		~	Run Sta Sto		IIII III
Sequence ID/ Work Center ID		peration . escription			Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr D3560 100 Bandsaw Jeaspa Bandsaw	Revisio Rev D	AND SAW	ks 15.500" long	· ************************************	0.00 0.00	£, 11/0	57/2	le	\$	Ø		
HAAS I HAAS CNC vertical ma		2-C'sink		5 Rev: $\triangle \triangle$	0.00 0.00 & Dwg D3560 Rev: Der dwg D3560	- JL 11-07	-27		8	d		
120 QC Quality Control	Q	C2- Inspect parts o Memo	ff machine FAI/F	AIB	0.00 .SL	- 11-07-27			8	ø		

ê .

...

Dart Aerospace i	Ltd
------------------	-----

Dait Aci	Ospace	LLU							<i>;</i>	
W/O:			W	ORK ORDER CHANG	ES				<i>,</i>	
DATE	STEP	PRO	OCEDURE CH	IANGE	I	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			,							
Part No	•	PAR #:			_ NCR:	Yes N	o DQ	A:	_ Date: _	
	R	esolution:	Disposit	ion:	_ QA: N	VC Clo	sed:		Date: _	
NCR:		,	WORK OR	DER NON-CONFORMA	ANCE ((NCR)				
DATE	STEP	Description of NC		Corrective Action Secti			Verific	ation	Approval	Approval
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
									:	
			·							
							·			
,										
		·								

Work Order ID 71949

Thursday, July 14, 2011 10:02:12 AM



Page 2

Item ID:

D3560-043

Accept



Setup Start



Stop

Start Date:

Required Date: 7/22/2011

Revision ID:

Item Name:

7/14/2011

Arm Weldment

Start Qty: 4.00

Req'd Qty: 4.00



Cust Item ID:

Customer:

Tool ID

Reference:

A	nn	rov	als:	•

Process Plan: Date: Tooling:

0.00

0.00

Date:

Run

Start

Date:_____

SPC (Y/N):

Date:

Tool # Plan

Stop

Reject

Number Stamp

Insp.

Reject

Sequence ID/ Work Center ID

130



QC

Operation Description

QC8- Inspect parts - second check

Memo

Set Up/ **Run Hours** 0.00

BA 11/07/28

Code Qty Qty

Accept

Quality Control

140



Large Fab

Large Fab

0.00

1-Weld assembly as per dwg D3560

STEP:

Memo

1- clean material (buff bracket and bottom of arm with blue pad)

- 2- set up bracket and arm on jig
- 3- preheat bracket and arm with torch
- 4- clean before welding with brush
- 5- set up machine to 135 amps
- 6- weld across bottom and top ends
- 7- reheat with torch (65 deg C)
- 8- on one side weld from bottom to top half way
- 9- same for other side (half way)
- 10- from half way point weld the rest of the first side (ease off pedal near end)

near end)

11- same for remaining side (ease off pedal

11.08.04

ospace	Liu								
		W	ORK ORDER CHANG	ES					
STEP	PRO	OCEDURE CHA	NGE	В	У	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	PAR #:	Fault Cate	gory:	_ NCR: \	es N	lo DQ	A:	_ Date: _	
R	esolution:	Dispositio	n:	QA: N/	C Clos	sed:		Date: _	
		WORK ORD	ER NON-CONFORM	ANCE (N	ICR)				
STED	Description of NC					Verific	cation	Approval	Approval
0121	Section A	Initial Chief Eng	Action Description Chief Eng			Secti	on C	Chief Eng	QC Inspector
-									
				,					
	STEP	Page in the page of NO	STEP PROCEDURE CHA PROCEDURE CHA PAR #: Fault Cate Resolution: Dispositio WORK ORD STEP Description of NC Section A	WORK ORDER CHANGE PROCEDURE CHANGE PROCEDURE CHANGE PAR #: Fault Category: Resolution: Disposition: WORK ORDER NON-CONFORM STEP Description of NC Section A Corrective Action Section A Corrective Action Description	WORK ORDER CHANGES STEP PROCEDURE CHANGE B PAR #: Fault Category: NCR: Y Resolution: Disposition: QA: N/ WORK ORDER NON-CONFORMANCE (NOTE) STEP Description of NC Corrective Action Section B Initial Action Description Si	WORK ORDER CHANGES STEP PROCEDURE CHANGE By PAR #: Fault Category: NCR: Yes N Resolution: Disposition: QA: N/C Clos WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC	WORK ORDER CHANGES STEP PROCEDURE CHANGE By Date	WORK ORDER CHANGES STEP PROCEDURE CHANGE By Date Qty PAR #: Fault Category: NCR: Yes No DQA: Resolution: Disposition: QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Corrective Action Section B Verification Section C Section C Section C	WORK ORDER CHANGES STEP PROCEDURE CHANGE By Date Qty Chief Eng/Prod Mgr PAR #: Fault Category: NCR: Yes No DQA: Date: PAR #: Disposition: QA: N/C Closed: Date: Date: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Section A Initial Action Description Sign & Section C Chief Eng / Chie

Work Order ID 71949

Thursday, July 14, 2011 10:02:12 AM



Page 3

Item ID:

D3560-043

Accept



Setup Start

Stop



Revision ID:

Item Name:

Arm Weldment

Start Date:

7/14/2011

Start Oty: 4.00

Required Date: 7/22/2011

Req'd Qty: 4.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: Date:

Memo

Memo

Date:_____

Tooling:

SPC (Y/N):

Date:

Date:

Run

Start Stop

Sequence ID/ **Work Center ID**

150

QC

Quality Control

Operation Description

QC5- Inspect part completeness to step on W/O

Set Up/

Run Hours

Tool ID

Tool # Plan Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

160

Quality Control

QC9- Inspect visual per QSI004- Fusion Welds

0.00

0.00

8 & Benjoe/of

170

HandFinish

Hand Finishing

Chemical Conversion Coat per OSI005 4.1

0.00

Memo

0.00

8× 9 m/4/08/08

- air Aci	oopaoc	Liu							
W/O:			N	ORK ORDER CHANGE	ES		· · · · · · · · · · · · · · · · · · ·		
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									
Part No	<u> </u>	PAR #:	Fault Ca	tegory:	NCR: Yes	No DQ	A:	_ Date: _	
	R	esolution:	Disposit	ion:	QA: N/C CI	osed:		Date: _	
NCR:			WORK OR	DER NON-CONFORMA	NCE (NCF	R)			
DATE	STEP	Description of NC	in this a	Corrective Action Section	on B Sign 8		cation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Date	Secti	ion C	Chief Eng	QC Inspector
			٠.	• 🔍					
·									

W۵	rk (Ord	er	ID	71	949
* * */				117	/ 1	, ,

Thursday, July 14, 2011 10:02:12 AM



Page 4

Item ID:

D3560-043

Accept



Setup Start



Revision ID:

Item Name:

Arm Weldment

Start Date:

7/14/2011

Start Oty: 4.00

Required Date: 7/22/2011

Req'd Qty: 4.00



Cust Item ID:

Customer:

Tool ID

Reference:

Approvals:

Process Plan: _____ Date:

Tooling:

Date:

Run

Start

Stop

Stop

Sequence ID/

Work Center ID

Operation

Description

Date:

SPC (Y/N):

Set Up/

Run Hours

Date:

Reject Accept

Insp. Reject

180

QC

Memo

QC3- Inspect Part Finish

0.00

0.00

Tool # Plan Qty Code

Oty

Number Stamp

Quality Control

190

Small Fab

Small Fab

Memo

Memo

0.00

0.00

Small Fab

1-Press bushing in D3560 arm per dwg D3562

200

QC

Quality Control

QC5- Inspect part completeness to step on W/O

Duit Ac	ospace	Liu							
W/O:			WOI	RK ORDER CHANGE	S	•			
DATE	STEP		CEDURE CHAN	GE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Catego	ory:	NCR: Yes	No DQA:	*	_ Date: _	
	R	esolution:	Disposition:		QA: N/C CIG	osed:		_ Date: _	
NCR:		V	VORK ORDE	R NON-CONFORMAL	NCE (NCR)			
DATE	STEP	Description of NC		orrective Action Section		Verifica	tion	Approval	Approval
- DAIL	O.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	C	Chief Eng	QC Inspector
-									
			·						·
· · · · · · · · · · · · · · · · · · ·									
	1					Ī	1		ļ

Item ID:

D3560-043

Accept



Setup Start

Stop



Revision ID:

Item Name:

Arm Weldment

Start Date:

Required Date: 7/22/2011

Start Qty: 4.00 7/14/2011

Req'd Qty: 4.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date: Date: Run

Start Stop



Sequence ID/

Date:

SPC (Y/N):

Set Up/

Run Hours

Tool ID

Tool # Plan

Accept Qty Code

Reject Qty

Reject Insp. Number Stamp

Work Center ID

210

Packaging

Packaging

Operation -Description

Identify as per dwg & Stock Location: M4

Memo *** STOCK IN STEP CELL***

0.00

0.00

11.08.10.

220

Quality Control

QC21- Final Inspection - Work Order Release

Memo

0.00

0.00

VII-08-11

Dail Ae	ospace	Liu							
W/O:			WO	RK ORDER CHANG	GES				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	A:	Date: _	-
	R	esolution:	Disposition	i:	QA: N/C CI	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCF	R)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sec Action Description Chief Eng	stion B Sign & Date	Verific Secti	cation on C	Approval Chief Eng	Approval QC Inspector
					:				
				<u> </u>					·

Picklist Print Thursday, July 14, 2011 10:02:18 AM Work Order ID: 71949 Parent Item: D3560-043 Parent Item Name: Arm Weldment Start Date: 7/14/2011 Required Date: 7/22/2011 Start Qty: 4.00 Required Qty: 4.00 IPP Rev:A New Issue 07.05.24 EC **Comments:** EC IPP Rev B ECN 987 07.10.09 DD verified by: EC IPP Rev:C ECN1048 07-12-18 Component Item ID/ Replacement Mfg/ Bin Primary Unit of Qty on Qty per Kit Total Last Route Qty Date Item Name Hand Item ID Purch Item Location Location Seq ID Measure **Qty** Issued-Issued D2808 100 17.0000 No Each Manufactured Bushing Location Loc Qty Loc Code GA 32896 2 15 ST023 69609 3 12 M6061T6B0.500X05.00 5.452632 Purchased No 140 35.1350 1.295 KK 11/07/26 6061-T6 Bar .500 x 5.00

No

Manufactured

Location	Loc	e Qty	Loc Code
MAT004		35.135	
112154		6.935	
7117933		28.2	
	190	Each	49.0000

Page 1

Status

10.33

D3592-1

Plate

Location Loc Qty Loc Code WA002 47015 2 48517 47

Duit Aci	Jopase	·							
W/O:			WC	RK ORDER CHANGE	ES				
DATE	STEP	PROC	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	·	PAR #:	_ Fault Cate	gory:	NCR: Yes	No DQA	٨:	_ Date: _	
	R	esolution:	_ Dispositio	n:	QA: N/C Cl	osed:		Date: _	
NCR:		W	ORK ORDI	ER NON-CONFORMA	NCE (NCR)		_ 100 000000	
DATE	STEP	Description of NC	<u> </u>	Corrective Action Section		Verific		Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	on C	Chief Eng	QC Inspector
	·								

DART AEROSPACE LTD	Work Order:	71949
Description: Arm	Part Number:	D3560-4
Inspection Dwg: D3560 Rev: D		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST


X	First Article		Prototype
---	---------------	--	-----------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments		
Ø0.507	+0.000/-0.001	-5065			M9526E			
Ø0.196	+0.005/-0.001	.197			Vern JL3			
Ø1.000	+0.010/-0.001	1-002			•			
Ø0.900	+0.010/-0.001	903			_			
0.500	+/-0.010	.487			-	stak mal'		
0.250	+/-0.010	.250						
0.275	+/-0.010	-244	//	_	-			
0.188	+/-0.010	-187			Mic 1-4			
1.750	+/-0.010	1.450			`			
1.702	+/-0.010	1-702	/, /		-			
Ø0.385 x 100°	+/-0.010 x 0.5°	380×100			,			
0.250 Deep	+/-0.010	-254						
		,						
-								

Measured by:	SL	Audited by:	B.A	Prototype Approval:	N/A
Date:	11-07-27	Date:	11 07 28	Date:	N/A


Rev	Date	Change	Revised by	Approved
Α	07.01.17	New Issue	KJ/JLM	
В	07.06.13	Dimensions updated per Dwg Rev B	KJ/JLM ,	
C	10.02.02	Dimensions updated per Dwg Rev C	KJ 🚧	

Dail Ac	ospace	Liu							
W/O:			WC	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	ult Category: NCR: Yes No DQA:				Date: _	
	R	esolution:	Disposition	າ:	_ QA: N/C C	losed:		Date: _	
NCR:			WORK ORDI	ER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC			tion B	Verific	cation	Approval	Approval
DATE	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector
								:	
									,




i .*


	oopao.	J = 1.4							
W/O:			WC	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			· · · · · · · · · · · · · · · · · · ·						
	1		a				.		
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	Date: _	
	R	Resolution:	Dispositio	n:	_ QA: N/C C	losed:		Date: _	
NCR:			WORK ORDI	ER NON-CONFORMA	ANCE (NCI	7)			
DATE	CTED	Description of NC			ion B	Verific	cation	Approval	Approval QC Inspector
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Secti		Chief Eng	
								<u> </u>	
		<u>}</u>							·




W/O:		,	W	ORK ORDER CHANG	ES				···
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Car	egory:	NCR: Yes	No DQ	A:	_ Date: _	
	R	esolution:	Dispositi	on:	_ QA: N/C Cld	sed:		Date: _	
NCR:			WORK ORI	DER NON-CONFORMA	ANCE (NCR)			
DATE	STEP	Description of NC		Corrective Action Secti		Verification		Approval	Approval
	O.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	on C	Chief Eng	QC Inspector
	ļ								
									·



	p								
W/O:			WC	ORK ORDER CHANGE	S				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						-			
Part No:		PAR #:	Fault Cate	gory:	NCR: Yes	No DQ			
	R	esolution:	Dispositio	n:	QA: N/C CI	osed:		Date:	
NCR:	* ,		WORK ORD	ER NON-CONFORMAI	NCE (NCF	R)			
DATE	STEP	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti		Chief Eng	QC inspector
									:



W/O:			WO	RK ORDER CHAN	GES					
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector
								i		
						į				
										
Part No		PAR #:	Fault Cate	gory:	NCR:	Yes N	o DQ	A:	_ Date: _	
		esolution:								
NCR:			WORK ORDE	R NON-CONFORM	IANCE	(NCR)		<u> </u>		
DATE	STEP	Description of NC			ection B		Verific	ation	Approval	Approval
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	1	Sign & Date	Secti		Chief Eng	QC Inspector
		·								
•										
				-						



Dart Aerospace Ltd	Dart	Aeros	pace	Ltd
---------------------------	-------------	--------------	------	-----

Dart Aei	ospace	Lia							
W/O:			V	ORK ORDER CHANGES	3				
DATE	STEP	PROC	CEDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	,								
			·			4.2			
Part No	•	PAR #:	_ Fault Ca	tegory:	NCR: Yes	No DQ	A:	_ Date: _	· · · · · · · · · · · · · · · · · · ·
	R	esolution:	_ Disposit	lon:	QA: N/C CI	osed:		Date: _	
NCR:	.*	W	ORK OR	DER NON-CONFORMAN	CE (NCR	R)		er,	
DATE	OTED	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		on C	Chief Eng	QC Inspector
						*	* the		
		•							
			•						
		ge rests	,						
			4.3						